

**Marsh Oaks Community Center
Hardening Project Photo Documentation
HLMP Grant No. DEM-HL00106
June 17, 2025**



North Facing Front of Building



North Facing Front of Building



Store Front Doors at Building Rear



Northeast Corner



Southeast Corner



Eastern Side of South Wall



Center of South Wall



Southwest Corner



Western Side



Northwest Corner



North Wall



Rafter Clips – North Wall (Typ)



Eastern Side of North Wall



Door & Windows at Building Front, View to West



Store Front Doors & Windows at Building Front, View to East



Store Front Doors & Windows at Building Front, View towards the West



Windows at Northeast Corner